

Littelfuse, Inc. 8755 West Higgins Road, Suite 500 Chicago, IL 60631 USA (773) 628-1000

Product Discontinuation Notice PDN No.: 41350

Recommended replacement

April 28th, 2020	Apri	il	28th.	, 2020
------------------	------	----	-------	--------

IXYS product type:

To: Our Valued Customers,

Littelfuse would like to notify you our decision to obsolete the following parts:

Type

	MG12100D-BA1MM MG12105S-BA1MM MG12150D-BA1MM MG12200D-BA1MM MG12300D-BA1MM MG1250S-BA1MM MG1275S-BA1MM MG06100S-BR1MM	MG12100S-BN2MM MG12100S-BN2MM MG12150S-BN2MM MG12200D-BN2MM MG12300D-BN2MM No replacement MG12100S-BN2MM No replacement			
Reason:	Die discontinuation				
Last time order date:	Not available				
Internal Reference:	LFPCN#41350				
In case of any question, please contact:					
Initiator	Title/Function	Date	e-mail		
Andreas Laschek-Enders	PM	April 28th, 2020	alaschek-enders@littelfuse.com		
IXYS Semiconductor GmbH Edisonstr. 15 D-68623 Lampertheim Phone: +49-6206-503-201 Fax: +49-6206-503-627					
Customer response:	(please fill in and re	turn by e-mail, fax or i	mail within 4 weeks)		
for further questions / information	on Company:				
please comment	Name & Position:				
	Phone / Fax No.:				
Comments:					

page 1 of 1 4.14F14a